| 2001 No. | Current No. | Title | Last Revision Date |
|---|---|---|---|
| | | **STREET** | |
| 101 | 101 | Cross Gutter | 2-25-14 |
| 102 | 102 | Sidewalk Details | 2-25-14 |
| 103 | 103 | R/W Modifications Around Access Ramps | 8-9-01 |
| 104 | 104 | Residential, Commercial, Industrial Driveway | 2-25-14 |
| 105 | 105 | Street Cross Sections | 1-25-16 |
| 106 | 106 | Residential Cul-de-sacs and Knuckle Intersection | 3-7-01 |
| 107 | 107 | Curb and Gutter | 2-25-14 |
| 108 | 108 | Guardrail | Deleted |
| 109 | 109 | Street Name Sign | 8-9-01 |
| 110 | 110 | Standard Tree Well | 3-7-01 |
| 111 | 111 | Temporary Barricade | 3-7-01 |
| 112 | 112 | Trench Backfill | 1-16-16 |
| 113 | 113 | Pipe Laying in Trenches | 2-25-14 |
| 114 | 114 | Asphalt Concrete | 6-24-14 |
| 115 | 115 | Standard Alley Intersection | 2-25-14 |
| 116 | 116 | Not Used – became part of 105 | |
| 117 | 117 | Bus Turnout | 6-5-01 |
| 118 | 118 | Access Ramps | 3-12-01 |
| 119 | 119 | Street Sign | 3-12-01 |
| 120 | 120 | Trench Failure | 2-25-14 |
| 121 | 121 | Disabled Parking Space Layout | Deleted |
| 122 | 122 | Driveway Spacing | Deleted |
| 123 | 123 | Right-in, Right-out Access Design | Deleted |
| 124 | 124 | Right-in, Right-out, Left-in Access Design | Deleted |
| 125 | 125 | Right-in, Right-out, Left-out Access Design | Deleted |
| 126 | 126 | Right-in, Right-out, Left-in Median Design | Deleted |
| 127 | 127 | Median Design – Restrict Exiting Left Turns | Deleted |
| 128 | 128 | Access Design with Median Divider | 6-12-01 |
| 129 | 129 | Access Grades | 6-5-01 |
| 130 | 130 | Street Geometrics | 6-5-01 |